


Pioneer XCY Installation Configuration

Revision Number: 03-300-009.01

Plug in equipment upon receipt to verify functionality.



VeriFone Adapter



Serial to 3rd party POS

Auxiliary Network Port

Black Ethernet cable from VeriFone Adapter to POS (only applicable to VeriFone POS applications)

3rd Party Point of Sale

Ruby/Sapphire, Pinnacle, Palm, Radiant, etc.

Network Switch



(Not supplied by Triple E)


Pioneer

Ethernet cable (not supplied by Triple E) from Modem/Router to Pioneer



Monitor and keyboard (not supplied) required for training

9-Pin Omni Cable to COM1 on Pioneer (RJ45 side to Pilot)



Pilot Terminal



(Optional Equipment)